

Tolerance Values as a Function of Temperature for 100Ω sensors

The newer standard, IEC 60751 Edition 2.0 2008-07 introduces a the published standards. new scheme of tolerance class.

For Wire wound resistors W0.1 W0.15	Temperature Range °C -100 to 350 -100 to 450	Tolerance, °C ±(0.1 + 0.0017 t) ±(0.15 + 0.002 t)
W0.15 W0.3	-100 to 450 -196 to 660	±(0.3 + 0.005 t)
W0.6	-196 to 660	±(0.6 + 0.01 t)

Note that W0.15 and W0.3 have a tolerance of the same magnitude as the earlier Class A & B but are valid over narrower temperature ranges.

Note: Class A and Class B relate to IEC751 1983 / BSEN 607511996. The vastmajority of TDI customers selecttolerances tighter than

Other Tolerances: These have been commonly specified as being a fraction of the Class B, now W0.3 tolerance, also known by many as DIN B from the earlier DIN 43760 standard.

Interchangeability at	
0°C ±0.05% ±0.03% ±0.02% ±0.01%	1/2 Class B (or DIN B) 1/3 Class B (or DIN B) 1/5 Class B (or DIN B) 1/10 Class B (or DIN B)

As the sensor is used further away from 0°C these errors can be expected to rise in accordance with an alpha uncertainty of ±3ppm.

Images shown here are actual size. All measurements in millimeters. All tolerances 0.1% at 0°C.

Model Number		Ceramic Length	Ceramic Diameter	Sensing Length
P100/7040		70	4	65 ±1
P100/5024 P2100/5024	0	50	2.4	47 ±1
P100/5015				
P2100/5015	0	50	1.5	47 ±1
P100/3045		30	4.5	27 1
P2100/3045		30	4.5	27 ±1
P100/3038		30	3.8	27 ±1
P2100/3038		30	5.0	27 ±1
P100/2532	0 ===	25	3.2	22 ±1
P2100/2532		25	5.2	ZZ ±1
P100/2528	0 ===	25	2.8	22 ±1
P2100/2528		25	2.0	22 ±1
P100/2524	0	25	2.4	22 ±1
P2100/2524		23	Z. 4	22 11
P100/2516	0	25	1.6	22 ±1
P2100/2516	0	23	1.0	ZZ ±1
P100/2515	0	25	1.5	22 ±1
P2100/2515	0	25	1.5	ZZ ±1
P100/2020	^	20	2.0	17 +1
P2100/2020	0	20	2.0	17 ±1
P100/1545		15	/ F	10 .1
P2100/1545		15	4.5	12 ±1
P100/1532	^ <u></u>	15	7.0	10 :1
P2100/1532		15	3.2	12 ±1
P100/1530				
P2100/1530		15	3.0	12 ±1
P100/1528				
P2100/1528		15	2.8	12 ±1
P100/1524				
P2100/1524		15	2.4	12 ±1
P100/1520				
P2100/1520	0	15	2.0	12 ±1
P100/1516				
P2100/1516	0 ===	15	1.6	12 ±1
P100/1516/16 square				
,		15	1.6	12 ±1
P100/1515				
P2100/1515 _P100/1512	0	15	1.5	12 ±1
P100/1512				
	0	15	1.2	12 ±1
P100/1509	0	15	0.9	12 ±1
P100/1508	0	15	0.8	12 ±1
P100/1016	0	10	1.6	8 ±1
			-6	
P100/1016/5 Flat		10	5(W) x 1.6 (H)	10 ±1
D100 h010				
P100/1012	0	10	1.2	8 ±1
Dana ha a s				
P100/1008	•	10	0.8	8 ±1
,				
P100/0815		08	1.5	8 ±1
P100/0620	0 ==	06	2.0	6 ±1
,				
P100/0445		04	4.4	3 ±1